

SAFETY INSPECTION REPORT IN FAVOUR OF:

Name of Building:
 Name of the Owner/Applicant
 Address/Location of the Structure:
 Contact No. of Owner/Applicant and mail id
 Year of Construction
 Building Use with Name of Prominent Users:
 Purpose of issuance of Certificate:
 Name of Inspecting Engineer with Contact No. and e-mail:


G.D GOENKA PUBLIC SCHOOL
BLA
ANWER SULTANA CHARITABLE TRUST
Near Jamkash Sengrama.
7006324961
2020-21
School Purposes.
UPGRADATION / AFFILIATION
ABDUL QAYOUM (AEE R&B) BLA
7006355058

VISUAL INSPECTION:

General Observations:

S.No	DESCRIPTION	REMARKS
1.	Type of Building	Fewer storeyed concrete buildings
2.	Age of Building	05 years
3.	As per Building Permission	05 years.
4.	As per Physical Assessment by Inspecting Officer	-
5.	No of wings	-
6.	Mode of Use	School
7.	No. of Stories	2+4 G+4 g/f
8.	Architectural Plan Name of the Architect	-
9.	Structural Plan Name of the Consultant	-
10.	Building Plan Approval Date	03/03/2010.
11.	Completion Certificate Date	-
12.	Last Repair Date	-
13.	Details of Repair.	-

* Age Proof supported by documents 2(i) or 2(ii) or 2(iii).


 Signature of Inspecting
 Junior Engineer

Signature of Inspecting
 Assistant Executive Engineer
 (R&B) Sub Division
 Baramulla Kashmir

Structural Observations:

No	DESCRIPTION	LOCATION OF COMPONENT	GRADE	REMARKS
	FOUNDATION			
	Foundation Settlement/Timber Rot			
	Floor Settlement			
	Foundation exposed to aggressive environment like water logging/dampness etc.			
A	SETTLEMENT/TILT DEFORMATION			
1	Column			
2	Walls			
B	CRACKS			
1.	Column	N/L	X	X
2.	Beams			
3.	Slab	2	2	2
4.	Plaster			
5.	External wall			
6.	Internal wall	2	2	2
C	CORROSION OF STEEL			
1.	Column			
2.	Beam			
3.	Slab			
D	LEAKAGES AND DAMPNES AND WATER PROOFING			
1.	External wall	2	2	2
2.	Toilet	2	2	2
3.	Terrace	2	2	2
4.	Top floor slab	2	2	2
5.	Inspection of overhead water tank	2	2	2
6.	Inspection of underground water tank	2	2	2
7.	Leakages & damages plumbing lines/waterlines, drainage lines	2	2	2

Signature of Inspecting
Junior Engineer

Signature of Inspecting
Assistant Executive Engineer
Assistant Executive Engineer
(R&B) Sub Division
Baramulla Kashmir

FIRE SAFETY			
	Fire gap on each side i.e. North, South, East and West.	To be reported by Concerned Fire and Emergency Services Department	
	Number of Exits		
	Sufficient width of Stair Case for safe exit of inhabitants		
	Provision of ramps (if any)		
	Status of Heavy Suspended Fixtures Such as Heavy false Ceilings etc.		
E	DEFLECTION		
1.	Beam		
2.	Slab		
3.	Overloading on slab		
4.	Cantilever deflection		
F	CONDITION OF OTHER COMPONENTS		
1	Staircase		
2.	Balcony		
3.	Flooring		
4.	Ducts		
5.	Terrace		
6.	Plumbing System		
7.	Electric Supply Line		
8.	Water Supply Line		


* The report regarding defects to be duly supported by photographs which shall also include photographs of structure from all four sides.

Payment of Rs 2000/- has been received vide G.R No. 0881017 Dated: 29/08/2022

Comments/Notations:

The buildings appears New Construction
and was found good for schooling purposes.


Signature of Inspecting
Junior Engineer


Signature of Inspecting
Assistant Executive Engineer
Assistant Executive Engineer
(R&B) Sub Division
Baramulla Kashmir

Based upon the information collected on this form and in light of recorded above at S.No. _____, _____, _____, the structure is **Sound/ Exhibits Rectifiable Defects/Non-Rectifiable Defects** with Major Distress.

The Corrective Action in respect of rectifiable Defects if required above are anticipated to be completed by _____


CERTIFICATE


The Structure in the opinion of the undersigned is hence assessed **Safe/Unsafe** for intended functional use based on Detailed Safety Inspection Report subject to required Corrective actions in case of identified rectifiable Defects.


The safety certificate is valid for **One Year** or date of occurrence of a natural disaster or an act of Major structural distress specific to the structure or anticipated date of completion of identified Corrective Actions if not completed, whichever is earlier.

Note:

This safety inspection report is based on absolute visual inspection of the structure, the information and explanations as observed and as obtained from the surroundings and to the best of the knowledge and belief of the inspecting officers and shall not be treated as an alternate to comprehensive destructive Structural Inspection. The R&B Department shall not be responsible for any loss of life and property due to any accident/mismanagement/ negligent maintenance/ overloading and misuse of the structure and all such eventualities/occurrences



Signature of inspecting
Junior Engineer


Executive Engineer
(R&B) Division Baramulla


Assistant Executive Engineer
(R&B) Sub Division
Baramulla Kashmir

I acknowledge receipt of this report.

No: **AEEB/1057** Dt: **29/08/2022**


Signature of Owner / applicant

Date: **29 / 08 / 2022**

Contact No: +91 **9419707549**

Mail Id : _____